

# ABINGDON TOWN COUNCIL

Report to	Environment, Amenities and Infrastructure Committee
Meeting date	8 <sup>th</sup> June 2026
Report author	Tim Badcock
Agenda item	11

## Cemetery & Outdoor Services Managers Report Bus Shelters

### 1. Purpose of the Report

1.1 Members are asked to consider the report.

### 2. Summary

2.1 Following a meeting of the working group where the conditions report was considered the COSM was requested to nominate 5 shelters for repair and 5 shelters for replacement.

### 3. Action required

3.1 Resolution to repair and replace the recommended shelters and obtain quotations for the proposed works to present to the next meeting of this committee.

### 4. Link to strategic plan and objectives

4.1 The provision and maintenance of bus shelters have a positive impact on the councils four key objectives -

#### **Our key objectives:**

1. To respond effectively and speedily to the climate emergency.
2. To develop a resilient, sustainable town which will provide a home for residents now and in the future.
3. To manage the Council's assets efficiently and effectively to meet for the needs of the community now and in the future.
4. To work with community partners to support those who are vulnerable and in need and to create opportunities to increase social inclusivity.

5. **Background**

- 5.1 The council have received an in-depth condition report from Externiture and have bus usage records for buses using these stops.
- 5.2 A working party was convened to consider reports and propose future works and create a life cycling of the shelters.

6. **Key information and options**

- 6.1 Members are requested to consider the following proposals and resolve to request the COSM to obtain quotes for the works.
- 6.2 It is officer recommendation to **replace** shelters at the following locations
- Radley Road – Swinburn Road
  - Radley Road – Norman Avenue
  - Oxford Road – Our Lady’s (Northbound)
  - Oxford Road – South Avenue (Northbound)
  - Preston Road – Landseer Walk
- 6.3 It is officer recommendation to **repair** shelters at the following locations
- Stratton Way – (southbound)
  - Drayton Road - Morland Gardens following recent vandalism
  - Wootton Road – John Mason School (Northbound) replace missing glass for solid panels
  - Wootton Road – John Mason School (Southbound) replace missing lower glass for solid panels
  - Wootton Road – Evelin Road

7. **Climate change/green implications**

- 7.1 Provision of clean, tidy bus shelters in the right locations promotes green travel.

8. **Financial/budget implications**

- 8.1 Balance of 301/4791 Capital Purchases: Bus Shelters - £20,000  
Balance of 301/4992 Bus Shelter Maintenance - £7000

9. **HR implications**

No additional staffing requirements.

10. **Supporting papers and appendices**

None